

LEXUS				
モデル	型式		補修用センサー	
ES	ES300 h	AXZH10	2018 - 2022	TO06030
		AXZH11	2022 -	
GS	GS250	GRL11	2011 - 2018	TO30060L
	GS300	ARL10	2011 - 2018	TO30060L
	GS300h	AWL10	2011 - 2018	TO30060L
	GS350	GRL10	2011 - 2018	TO30060L
		GRL15	2011 - 2018	
GS450	GWL10	2011 - 2018	TO30060L	
IS	IS250	GSE30	2013 - 2015	TO30060
		GSE35	2013 - 2016	TO30060
	IS300h	AVE30	2013 -	TO30060
		AVE35	2015 -	TO30060
	IS350	GSE31	2013 -	TO30060
	IS200t/IS300	ASE30	2015 -	TO30060
	IS500	USE30	2022 -	TO06030
LC	LC500	URZ100	2017 -	TO06030
	LC500h	GWZ100	2017 -	TO06030
LS	LS460	USF40	2012 - 2017	TO30060L
		USF45	2012 - 2017	TO30060L
	LS460L	USF41	2012 - 2017	TO30060L
		USF46	2012 - 2017	TO30060L
LS500h	GVF50	2017 - 2020	TO06030	
		2020 -		
	GVF55	2017 - 2020	TO06030	
		2020 -		
LS500	VXFA50	2017 - 2020	TO06030	
	VXFA55	2017 - 2020	TO06030	
LX	LX570	URJ201W	2015 - 2021	TO06030
	LX600	VJA310W	2022 -	TO06030
RC	RC200t	ASC10	2014 - 2017	TO30060
	RC300	ASC10	2017 - 2020	TO30060
			2021 -	TO06030
	RC300h	AVC10	2014 - 2020	TO30060
	RC350	GSC10	2021 -	TO06030
2014 - 2020			TO30060	
RC F	USC10	2014 - 2020	TO30060	
			2021 -	TO06030

LEXUS					
モデル	型式		補修用センサー		
RX	RX200t	AGL25W	2015 - 2017	TO06030	
		AGL20W	2015 - 2017		
RX300		AGL25W	2017 - 2022	TO06030	
		AGL20W	2017 - 2022		
RX450		GYL25W	2016 - 2018	TO06030	
		2019 - 2022			
RX450hL		GYL20W	2016 - 2018	TO06030	
		2019 - 2022			
RX350		TALA15	2022 -	TO06030	
		TALA10	2022 -	TO06030	
RX450h		AALH16	2022 -	TO06030	
RX450h+		AALH16	2022 -	TO06030	
RX500		TALH17	2022 -	TO06030	
UX	UX200	MZAA10	2018 - 2020	TO06030	
		2020 -			
UX250h		MZAH15	2018 - 2020	TO06030	
		2020 -			
UX250h		MZAH10	2018 - 2020	TO30060	
		2020 -			
NX	NX200t	AGZ10	2014 - 2018	TO30060L	
		AGZ15	2014 - 2018		
	NX300		AGZ10	2018 - 2021	TO30060L
			AGZ15	2018 - 2021	
NX300h		AYZ10	2014 - 2021	TO30060L	
		AYZ15	2014 - 2021		
NX250		AAZA25	2022 -	TO30060L	
		AAZA20	2022 -	TO30060L	
NX350		TAZA25	2022 -	TO30060L	
		AAZH25	2022 -	TO30060L	
NX350 h		AAZH20	2022 -	TO30060L	
		AAZH26	2022 -	TO30060L	
NX450 h		AAZH26	2022 -	TO30060L	

TOYOTA				
モデル	型式		補修用センサー	
Camry	2WD	AXVH70	2017 -	TO06030
	E-Four	AXVH75	2017 -	TO06030
Century		UWG60	2018 -	TO30060
Crown		AZSH21	2018 - 2022	TO30060
		GWS224	2018 - 2022	TO30060
Land Cruiser		URJ202W	2007 - 2021	TO06030
Plado		GDJ151W	2009 - 2021	TO06030
GR Yaris		GXPA16	2020 -	TO06030
Gran-Ace		GDH303W	2019 -	TO29005
Mirai		JPD20		TO06030
bZ4X		YEAM10		TO06030
		YEAM15		

●製品の仕様は予告なく変更になることがあります。



ONODANI
TIRE SERVICE SOLUTION

